



VIRLAB, S.A.

TEST CERTIFICATE

Delivered on: 13/01/2004

Reference: * DISPOSICIONES SOBRE MERCANCÍAS PELIGROSAS EN EL TRANSPORTE AEREO (MOPT) - Capítulo 4 – Ensayos de Idoneidad de los Embalajes

Laboratory Name: VIRLAB, SA

Laboratory Address: Polígono Industrial de Asteasu, Zona B – 44. Apartado 247
20159 ASTEAU (SPAIN)

Equipment tested: Clip-Lok Boxes Types CL-1, CL-2 and CL-3 from CLIP-LOK SIMPACK IBERICA in order to contain articles from Group Packing II where we can find the following articles (lithium batteries, electrolyte acid for cells, electric cells, and so on).

VIRLAB, S.A. certifies that the Clip-Lok Boxes CL1, CL2 and CL3 from CLIP-LOK SIMPACK IBERICA have been tested according to Chapter 4 of the above reference, performing the following tests:

- STAKING TEST: for this test four identical Clip-Lok Boxes are stacked one on each other with a maximum height of 2800mm, the height of each Clip-Lok Box is 700mm. The Boxes are maintained in this position for more than 24 hours without any apparent deterioration.
- FREE FALL TEST: the following free drop tests are performed from a height of 1,2 meters (Group Packing II)
 - First fall: straight against the bottom of the box
 - Second fall: straight against the top of the box
 - Third fall: straight against the longest lateral side of the box
 - Fourth fall: straight against the shortest lateral side of the box
 - Fifth fall: against one corner

The Clip-Lok Boxes passed the staking and free fall tests successfully, no failures nor structural damages have been detected during the tests that could limit their correct handling.

The tests on each of the Clip-Lok Box have been performed with an internal load of thin metal shell with the following gross weight:

- Clip-Lok Box type CL-1: 250 kg
- Clip-Lok Box type CL-2: 300 kg
- Clip-Lok Box type CL-3: 400 kg



In the test report number **241101** of VIRLAB, S.A., all the obtained information is included, with tables, figures, photographs and so on.

JOSÉ LUIS BAENA
Laboratory Engineer

**REPORT OF THE APTITUDE TESTS FOR PACKING OF
DANGEROUS GOODS FOR THE AIR TRANSPORT CARRIED OUT
ON CLIP-LOK BOXES TYPES CL-1, CL-2 y CL-3
FROM CLIP-LOK SIMPAK IBERICA, S.A.**

NOTA: As indicated in section 5.10.2 of Standard ISO/IEC 17025:1, it is stated that:

- The results of this report concern the samples tested solely and exclusively
- The Laboratory forbids the partial reproduction of this document without written authorisation.

Date	Carried out by:	Revised by:	VIRLAB, S.A.	Ctra. Villabona, Km 2,5
06.07.04			División URBAR INGENIEROS	20159 Asteasu (Guipúzcoa)
	José L. Baena	Juan A. Pérez	Tel.: +34 43 69 15 00	Fax: +34 43 69 26 67

INDEX

MEMORY

	<u>Page N°</u>
1.0 REPORT NUMBER	3
2.0 CLIENT	3
3.0 EQUIPMENT TESTED	3
4.0 REFERENCES	3
5.0 TEST PROCEDURE	4
6.0 DESCRIPCIÓN AND RESULTS OF THE TESTS	5
7.0 CONCLUSIONS	9

DRAWINGS AND PHOTOGRAPHS:

DRAWINGS	12 to 24
PHOTOGRAPHS NUMBER 1 TO 23	25 to 48

APPÉNDICES:

APPÉNDIX I: DAILY TEST SHEETS.	49 to 59
APPÉNDIX II: DISPOSICIONES SOBRE MERCANCÍAS PELIGROSAS EN EL TRANSPORTE AEREO (MOPT) - Capítulo 4 – Ensayos de Idoneidad de los Embalajes.....	60 to 65

1.0.- REPORT NUMBER

241101, comprising 65 sheets, made up of a Memorandum with Drawings, Photographs and two Appendices.

2.0.- CLIENT

CLIP-LOK SIMPAK IBERICA, S.A.
Ctra. N240 Pamplona-Huesca, km. 15-16
Cruce Campanas-Urtoz
31471-MONREAL (NAVARRA)

3.0.- EQUIPMENT TESTED

Test have been carried out on wooden boxes made of phenolic plywood of 18mm thickness with the following models and general dimensions:

- | | | | |
|---------|---------------------|---------|-------|
| • CL-1: | 800 x 600 x 700 mm | Weight: | 38 kg |
| • CL-2: | 1200 x 800 x 700 mm | Weight: | 59 kg |
| • CL-3: | 2400 x 800 x 700 mm | Weight: | 97 kg |

The Clip-Lok Boxes reached the Laboratory on 16-12-2003, carrying out the tests between the 19'th of December of 2.003 and the 12'th to 14'th of January of 2004.

4.0.- REFERENCES

The Clip-Lok Boxes have been tested according to the following standards:

- DISPOSICIONES SOBRE MERCANCÍAS PELIGROSAS EN EL TRANSPORTE AEREO (MOPT) - Capítulo 4 – Ensayos de Idoneidad de los Embalajes

5.0.- TEST PROCEDURE

The test whose results are described in this report were performed according to Chapter 4 of the Reference of Point 4, enclosed in **APPENDIX II**.

5.1.- STAKING TEST

All the packaging, except the bags, have to be submitted to the staking test.

Number of test samples: three test samples for prototype and manufacturer.

Test method: the test sample has to be submitted to an applied force on the top of the surface, equivalent to the total weight of identical packing that could be staked on it during the transport operation. The minimum height of stacking, including the test sample, has to be 3 meters. Each test has to last 24 hours.

Overpass test criterion: the test sample should not have losses of load. The test sample should not have signs of deterioration that could affect the security of the transport, or distortion that could reduce the resistance or cause the staking unstableness.

5.2.- FREE-FALL TEST

It is necessary to perform five falls for the plywood boxes.

- First fall: straight against the bottom of the box
- Second fall: straight against the top of the box
- Third fall: straight against the longest lateral side of the box
- Fourth fall: straight against the shortest lateral side of the box
- Fifth fall: against one corner

The height of fall for Packing Group II will be 1.2 meters.

Overpass test criterion: a small loss, through the fastening elements, during the fall, will not make the plywood box deficient, provising that no more losses could happen.

6.0.- DESCRIPTION AND RESULTS OF THE TESTS

6.1.- STAKING TESTS

The Laboratory has four plywood boxes of each of the following types CL-1, CL-2 and CL-3 filled with thin metal shell with the next gross weights:

- CL-1 250 kg, 250 kg, 250 kg y 250 kg
- CL-2 858 kg, 778 kg, 942 kg y 822 kg
- CL-3 1156 kg, 996 kg, 1032 kg y 1042 kg

The three different types of Clip-Lok boxes are staked on a horizontal surface, reaching a maximum height of 2800mm, because each Clip-Lok Box has a height of 700mm. The Boxes are stacked from the 19'th of December 2003 to the 12'th of January 2004 and during this period of time no records of losses of material and no indication of deterioration that could affect the security during transportation has been presented.

Photographs Nº 1 and 2 show the three type of Clip-Lok Boxes CL-1, CL-2 and Cl-3 staked.

6.2.- FREE-FALL TESTS

The Clip-Lok boxes are lifted by mean of slings to a total height of 1,2meters to let them fall by mean of a manual device on a flat concrete surface, obtaining the following results:

CLIP-LOK BOX TYPE CL-1 - First fall: straight against the bottom of the box
(Photograph Nº 3)

Comments: The Clip-Lok Box has not damaged its structural unit, keeping all the clips in their position.

CLIP-LOK BOX TYPE CL-1 - Second fall: straight against the top of the box (Photograph Nº 4)

Comments: The Clip-Lok Box has not damaged its structural unit, keeping all the clips in their position except one of them.

CLIP-LOK BOX TYPE CL-1 - Third fall: straight against the longest lateral side of the box (Photograph Nº 5)

Comments: The Clip-Lok Box has not damaged its structural unit, keeping all the clips in their position.

CLIP-LOK BOX TYPE CL-1 - Fourth fall: straight against the shortest lateral side of the box (Photograph Nº 6)

Comments: The Clip-Lok Box has not damaged its structural unit, keeping all the clips in their position.

CLIP-LOK BOX TYPE CL-1 - Fifth fall: against one corner – Inclination approx. 45° (Photograph Nº 7 and 8)

Comments: The Clip-Lok Box has not damaged its structural unit, two clips have jumped from their position and there has not been an important lost of product.

CLIP-LOK BOX TYPE CL-2 - First fall: straight against the bottom of the box (Photograph Nº 9)

Comments: The Clip-Lok Box has not damaged its structural unit, keeping all the clips in their position. Two clips have jumped from their position and there has not been an important lost of product and the central stopper gets incrust on the bottom of the box.

CLIP-LOK BOX TYPE CL-2 - Second fall: straight against the top of the box (Photograph Nº 10)

Comments: The Clip-Lok Box has not damaged its structural unit, keeping all the clips in their position and loosing a small amount of product.

CLIP-LOK BOX TYPE CL-2 - Third fall: straight against the longest lateral side of the box (Photograph Nº 11)

Comments: The Clip-Lok Box has not damaged its structural unit, keeping all the clips in their position and loosing a small amount of product.

CLIP-LOK BOX TYPE CL-2 - Fourth fall: straight against the shortest lateral side of the box (Photograph N° 12)

Comments: The Clip-Lok Box has not damaged its structural unit, keeping all the clips in their position.

CLIP-LOK BOX TYPE CL-2 - Fifth fall: against one corner – Inclination aprox. 45° (Photograph N° 13)

Comments: The Clip-Lok Box has damaged its structural unit, getting off all the clips from one side and loosing all the load.

CLIP-LOK BOX TYPE CL-2 - Fifth fall: against one corner – Inclination aprox. 45° (Photograph N° 14) – GROSS WEIGHT 300 kg

Comments: The Clip-Lok Box has not damaged its structural unit, jumping the clips from the lower part of the box and loosing a small amount of product. The clips have been placed again in their position rearming the box.

CLIP-LOK BOX TYPE CL-3 - First fall: straight against the bottom of the box (Photograph N° 15)

Comments: The Clip-Lok Box has not damaged its structural unit. Two clips have jumped from their position, there has not been an important lost of product and the central stoppers have got incrust on the bottom of the box.

CLIP-LOK BOX TYPE CL-3 - Second fall: straight against the top of the box (Photograph N° 16)

Comments: The Clip-Lok Box has not damaged its structural unit, keeping all the clips in their position.

CLIP-LOK BOX TYPE CL-3 - Third fall: straight against the longest lateral side of the box (Photograph N° 17)

Comments: The Clip-Lok Box has not damaged its structural unit, keeping all the clips in their position.

CLIP-LOK BOX TYPE CL-3 - Fourth fall: straight against the shortest lateral side of the box (Photograph N° 18)

Comments: The Clip-Lok Box has not damaged its structural unit, keeping all the clips in their position, there has not been an important lost of product.

CLIP-LOK BOX TYPE CL-3 - Fifth fall: against one corner – Inclination aprox. 45° (Photograph N° 19)

Comments: The Clip-Lok Box has damaged its structural unit, all the clips of the bottom part have jumped opening the lateral sides of the box, loosing all the load.

CLIP-LOK BOX TYPE CL-3 - Fifth fall: against one corner – Inclination aprox. 45° (Photograph N° 20) – GROSS WEIGHT 400 kg

Comments: The Clip-Lok Box has not damaged its structural unit, jumping the clips from the lower part of the box and loosing a small amount of product. The clips have been placed again in their position rearming the box.

7.0.- CONCLUSIONS

In the light of the tests performed, in accordance with the procedure indicated in Point 5.0, and of the results obtained described in point 6.0, the CLIP-LOK BOXES types CL-1, CL-2 and CL-3 from CLIP-LOK SIMPAC IBERICA, has satisfactorily passed the staking and free-fall tests that have been undergone, in order to contain articles from Group Packing II (lithium batteries, electrolyte acid for cells, electric cells, and so on).

Test have been carried out on the three different types of wooden boxes made of phenolic plywood of 18mm thickness, initially loaded with thin metal shell with the next gross weights:

- Clip-Lok Box type CL-1: 250 kg
 - Clip-Lok Box type CL-2: 750 kg
 - Clip-Lok Box type CL-3: 1000 kg
-
- **STAKING TEST:** for this test four identical Clip-Lok Boxes are stacked one on each other with a maximum height of 2800mm, the height of each Clip-Lok Box is 700mm. The Boxes are maintained in this position for more than 24 hours without any apparent deterioration that could affect the security during the transportation.
 - **FREE-FALL TESTS:** the following free-fall tests are performed from a total height of 1,2 meters:
 - First fall: straight against the bottom of the box
 - Second fall: straight against the top of the box
 - Third fall: straight against the longest lateral side of the box
 - Fourth fall: straight against the shortest lateral side of the box
 - Fifth fall: against one corner

The final gross weight for Clip-Lok Boxes CL-2 and CL-3 have been of 300 kg and 400 kg respectively in order to pass the Fifth fall against one corner.

The Clip-Lok Boxes passed staking and free-fall tests successfully, no failures nor important structural signs of deterioration that could affect the security of the transport have been detected during the tests that could limit their correct handling and that could affect the security during the transportation.

Asteasu (SPAIN), 6th July 2004

VIRLAB, S.A.
Division of URBAR INGENIEROS, S.A.

Revised

Juan A. Pérez
Juan Antonio Pérez
Head of Laboratory

Carried out

J. L. Baena
Jose Luis Baena
Engineer of Laboratory

DRAWINGS AND PHOTOGRAPHS

VIRLAB, S.A.

Division of URBAR INGENIEROS

REPORT NUMBER

241101

Page Number


12 / 65

DRAWINGS

Clip-Lok International Limited (4127193). This drawing is the property of Clip-Lok International Limited and any copying or dissemination without the prior written consent of Clip-Lok International Limited is prohibited. If you are in possession of a copy or disseminate this drawing without proper authority, legal proceedings may be taken against you. Clip-Lok International Limited, phone: fax:

Clip-Lok 4-WAY ISOMETRIC VIEW

martes, 24 de junio de 2003



4-WAY ISOMETRIC VIEW
martes, 24 de junio de 2003

Clip-Lok International Limited (4127193). This drawing is the property of Clip-Lok International Limited and any copying or dissemination without the prior written consent of Clip-Lok International Limited is prohibited. If you are in possession of a copy or disseminate this drawing without proper authority, legal proceedings may be taken against you. Clip-Lok International Limited, phone: fax:

REF CL-1



Client name	:	EJERCITO
Project code	:	(CL-1)
Clip-Lok reference	:	
External dimensions	:	600 x 800 x 700 mm
Internal dimensions	:	564 x 764 x 551 mm
Clip type	:	BIG
Total nr. of clips	:	16
Pallet type	:	FOUR WAY



ALL PANELS VIEW
martes, 24 de junio de 2003

Clip-Lok International Limited (412793) This drawing is the property of Clip-Lok International Limited and any copying or dissemination of it without the prior written consent of Clip-Lok International Limited is prohibited. You are in possession of a copy or dissemination of this drawing without proper authority, legal proceedings may be taken against you. Clip-Lok International Limited. Phone: Fax.

VIRLAB, S.A.



Division of URBAR INGENIEROS

REPORT NUMBER

241101

Page Number

14 / 65




Clip-Lok SimPak Ibérica S.R.L.
CAJAS PLEGABLES Y REUTILIZABLES

Client name	:	EJERCITO
Project code	:	CL-4
Top material	:	CONTRACHAPADO
Top thickness	:	18 mm
Side/end material	:	CONTRACHAPADO
Side/end thickness	:	18 mm
Bottom material	:	CONTRACHAPADO
Bottom thickness	:	18 mm

Clip-Lok International Limited ((4/27/03)) This drawing is the property of Clip-Lok International Limited and any copy or dissemination of it without the written consent of Clip-Lok International Limited is illegal. All rights reserved. Copy or dissemination of this drawing without prior authority, legal proceedings may be taken against you. Clip-Lok International Limited, phone, fax,

Clip-Lok
4-WAY PALLET SIDE & END VIEWS
martes, 24 de junio de 2003




Client name : EJERCITO
Project Code : CL-1
Number of Bearers: 3
Runner material: CONTRACHAPADO
Block material: PINO
Crossmembers : NONE

Handling : ALONG LENGTH
Pallet base height: 131 mm

Clip-Lok International Limited (4/27/93). This drawing is the property of Clip-Lok International Limited and any copying or dissemination of it without the prior written consent of Clip-Lok International Limited is prohibited. If you are in possession of a copy or disseminate this drawing without proper authority, legal proceedings may be taken against you. Clip-Lok International Limited. Phone: fax:

Clip-Lok
4-WAY PALLET - TOP VIEW
 martes, 24 de junio de 2003




Client name : EJERCITO
 Project Code : CL-A
 Number of Bearers: 3
 Runner material: CONTRACHAPADO
 Block material: PINO
 Crossmembers : NONE

Handling : ALONG LENGTH
 Pallet base height: 131 mm

Clip-Lok International Limited (4/27/93). This drawing is the property of Clip-Lok International Limited and any copying or dissemination of it without the prior written consent of Clip-Lok International Limited is prohibited. If you are in possession of copy or disseminate this drawing without proper authority, legal proceedings may be taken against you. Clip-Lok International Limited. Phone: fax.

Clip-Lok
WAY ISOMETRIC VIEW
artes, 24 de Junio de 2003


DEF CL-2



Client name	:	EJERCITO (CL2)
Project code	:	1
Clip-Lok reference	:	
External dimensions	:	1200 x 800 x 700 mm
Internal dimensions	:	1164 x 764 x 551 mm
Clip type	:	BIG
Total nr. of clips	:	20
Pallet type	:	FOUR WAY

Clip-Lok International Limited (412793). This drawing is the property of Clip-Lok International Limited and any copy or dissemination of it without the prior written consent of Clip-Lok International Limited is prohibited. You are in possession of a copy or possession of this drawing. If its copying or dissemination is unauthorized, legal proceedings may be taken against you. Clip-Lok International Limited. phone: fax.


Clip-Lok
ALL PANELS VIEW
martes, 24 de junio de 2003



Client name	: EJERCITO
Project code	
Top material	CONTRACHAPADO
Top thickness	: 18 mm
Side/end material	CONTRACHAPADO
Side/end thickness	: 18 mm
Bottom material	CONTRACHAPADO
Bottom thickness	: 18 mm

Clip-Lok International Limited (4/27/93). This drawing is the property of Clip-Lok International Limited and any copying or dissemination of it without the written consent of Clip-Lok International Limited is an infringement of copyright. You are in possession of a copy of this drawing without proper authority, legal proceedings may be taken against you. Clip-Lok International Limited, phone: (202) 293-1000.

Clip-Lok
4-WAY PALLET SIDE & END VIEWS
martes, 24 de junio de 2003



Client name : EJERCITO Project Code : CL-1
Number of Bearers: 3


Runner material: CONTRACHAPADO
Block material : PINO
Crossmembers : NONE

Handling : ALONG LENGTH
Pallet base height: 131 mm



4-WAY PALLET - TOP VIEW
martes, 24 de junio de 2003

Clip-Lok International Limited (4/27/93). This drawing is the property of Clip-Lok International Limited. It is illegal to copy or disseminate this drawing without prior written consent of Clip-Lok International Limited. If you are in possession of a copy of this drawing, please return it to Clip-Lok International Limited. Legal proceedings may be taken against you. Clip-Lok International Limited. phone: fax.



Client name : EJERCITO
Project Code : CL-2
Number of Bearers: 3

Runner material: CONTRACHAPADO
Block material: PINO
Crossmembers : NONE


Handling : ALONG LENGTH
Pallet base height: 131 mm

Clip-Lok International Limited (4/27/93). This drawing is the property of Clip-Lok International Limited and any copying or dissemination of it without the prior consent of Clip-Lok International Limited is prohibited. If you are in possession of copy or disseminate this drawing without proper authority, legal proceedings may be taken against you. Clip-Lok International Limited. Phone: +44 1270 622222




4-WAY ISOMETRIC VIEW
miércoles, 22 de octubre de 2003

Ref CL-3





Client name	:	EJERCITO (CL 3)
Project code	:	
Clip-Lok reference	:	2400 x 800 x 700 mm
External dimensions	:	2364 x 764 x 546 mm
Internal dimensions	:	
Clip type	:	BIG
Total nr. of clips	:	28
Pallet type	:	FOUR WAY




ALL PANELS VIEW
miércoles, 22 de octubre de 2003

Clip-Lok International Limited (#422793). This drawing is the property of Clip-Lok International Limited and any copying or dissemination of it without the prior written consent of Clip-Lok International Limited is prohibited. You are in possession of a copy or disseminate this drawing without proper authority, legal proceedings may be taken against you. Clip-Lok International Limited, phone: fax.




Client name	: EJERCITO	
Project code	:	
Top material	: CONTRACHAPADO	
Top thickness	: 18 mm	
Side/end material	: CONTRACHAPADO	
Side/end thickness	: 18 mm	
Bottom material	: CONTRACHAPADO	
Bottom thickness	: 18 mm	



4-WAY PALLET SIDE & END VIEWS

miercoles, 22 de octubre de 2003


Clip-Lok International Limited (442793) This drawing is the property of Clip-Lok International Limited
and any copying or dissemination of it by you without written consent of Clip-Lok International Limited
is prohibited. If you are in possession of copy or dissemiate this drawing without proper authority,
legal proceedings may be taken against you. Clip-Lok International Limited. phone: fax.



Client name : EJERCITO
Project Code : CL-3
Number of Bearers: 3


Runner material: CONTRACHAPADO
Block material: PINO
Crossmembers : NONE

Handling : ALONG LENGTH
Pallet base height: 136 mm



4-WAY PALLET - TOP VIEW
miércoles, 22 de octubre de 2003

Clip-Lok International Limited (4/27/93). This drawing is the property of Clip-Lok International Limited and any copying or dissemination of it without written consent of Clip-Lok International Limited is prohibited. If you are in possession of copy or disseminate this drawing without proper authority, legal proceedings may be taken against you. Clip-Lok International Limited, phone, fax,



Client name : EJERCITO
Project Code : CL-3
Number of Bearers: 3

Runner material: CONTRACHAPADO
Block material : PINO
Crossmembers : NONE

Handling : ALONG LENGTH
Pallet base height: 136 mm

VIRLAB, S.A.

Division of URBAR INGENIEROS


REPORT NUMBER

241101

Page Number

25 / 65

PHOTOGRAPHS



PHOTOGRAPH NUMBER 1

Side view of Clip-Lok Boxes Type CL-1, CL-2 and CL-3 before starting the staking test.

VIRLAB, S.A.


Division of URBAR INGENIEROS

REPORT NUMBER

241101


Page Number

27 / 65




PHOTOGRAPH NUMBER 2

Front view of Clip-Lok Boxes Type CL-1, CL-2 and CL-3 before starting the staking test.




PHOTOGRAPH NUMBER 3

*Front view of Clip-Lok Box CL-I ready to perform the first fall,
straight against the bottom of the box.*




PHOTOGRAPH NUMBER 4

*Front view of Clip-Lok Box CL-1 ready to perform the second fall,
straight against the top of the box.*




PHOTOGRAPH NUMBER 5

*Front view of Clip-Lok Box CL-1 ready to perform the third fall,
straight against the longest lateral side of the box.*




PHOTOGRAPH NUMBER 6

*Front view of Clip-Lok Box CL-1 ready to perform the fourth fall,
straight against the shortest lateral side of the box.*




PHOTOGRAPH NUMBER 7

*Front view of Clip-Lok Box CL-1 ready to perform the fifth fall,
against one corner.*




PHOTOGRAPH NUMBER 8

Detail of the deterioration of Clip-Lok Box CL-1, checking that the structural unit is OK.




PHOTOGRAPH NUMBER 9

*Front view of Clip-Lok Box CL-2 ready to perform the first fall,
straight against the bottom of the box.*



PHOTOGRAPH NUMBER 10

*Front view of Clip-Lok Box CL-2 ready to perform the second fall,
straight against the top of the box.*




PHOTOGRAPH NUMBER 11

*Front view of Clip-Lok Box CL-2 ready to perform the third fall,
straight against the longest lateral side of the box.*




PHOTOGRAPH NUMBER 12

Front view of Clip-Lok Box CL-2 ready to perform the fourth full, straight against the shortest lateral side of the box.




PHOTOGRAPH NUMBER 13

*Front view of Clip-Lok Box CL-2 ready to perform the fifth fall,
against one corner.*



PHOTOGRAPH NUMBER 14

Detail of the Clip-Lok Box CL-2 after the fifth fall, damaging the structural unit and loosing the load.



PHOTOGRAPH NUMBER 15

*Front view of Clip-Lok Box CL-2 ready to perform the fifth fall.
against one corner with a gross weight of 300 kg.*

VIRLAB, S.A.


Division of URBAR INGENIEROS

REPORT NUMBER

241101


Page Number

41 / 65




PHOTOGRAPH NUMBER 16

Detail of Clip-Lok Box CL-2 after performing the fifth fall with a gross weight of 300 kg, where it loose the clips of the bottom part but still maintain the structural unit.




PHOTOGRAPH NUMBER 17

*Front view of Clip-Lok Box CL-3 ready to perform the first fall,
straight against the bottom of the box.*



PHOTOGRAPH NUMBER 18

*Front view of Clip-Lok Box CL-3 ready to perform the second fall,
straight against the top of the box*



PHOTOGRAPH NUMBER 19

*Front view of Clip-Lok Box CL-3 ready to perform the third fall,
straight against the longest lateral side of the box.*

VIRLAB, S.A.


Division of URBAR INGENIEROS

REPORT NUMBER

241101

Page Number

45 / 65



PHOTOGRAPH NUMBER 20

*Front view of Clip-Lok Box CL-3 ready to perform the fourth fall,
straight against the shortest lateral side of the box.*

VIRLAB, S.A.


Division of URBAR INGENIEROS

REPORT NUMBER

241101

Page Number

46 / 65



PHOTOGRAPH NUMBER 21

*Front view of Clip-Lok Box CL-3 ready to perform the fifth fall,
against one corner.*

VIRLAB, S.A.


Division of URBAR INGENIEROS

REPORT NUMBER

241101


Page Number

47 / 65



PHOTOGRAPH NUMBER 22

Detail of the Clip-Lok Box CL-3 after the fifth fall, loosing the structural unit and the load.



PHOTOGRAPH NUMBER 23

*Front view of Clip-Lok Box CL-2 ready to perform the fifth fall,
against one corner with a gross weight of 400 kg.*

VIRLAB, S.A.

Division of URBAR INGENIEROS

REPORT NUMBER


241101

Page Number

49 / 65

APPENDIX I

DAILY TEST SHEETS.



HOJA	DE	INFORME N°:	INGENIERO DE ENSAYOS:
14	12.04	241101	<i>M. Pérez</i>

FECHA	HORA	OBSERVACIONES
14.12.04	21:00	El material se encuentra en el laboratorio al haber realizado ensayos con ese material anteriormente. Se dispone de la muestra de los siguientes dimensiones:
		* Cl - 1 => 500 x 600 x 200 mm 38 Kg
		* Cl - 2 => 1200 x 400 x 200 mm 50 Kg
		* Cl - 3 => 800 x 800 x 200 mm 92 Kg
		Se van a ensayar las probabilidades establecidas en la parte en el Capítulo 4 - Tabla de probabilidad de los factores de Disponibilidad sobre mediciones realizadas en el Transistor TI Affect (MOPF).
		Hoy se realizará dos tipos de ensayos:

FECHA	HORA	OBSERVACIONES
19-12-04		Examen de Apuntamientos : para la red de señales los cuatro enfoques de cada tipo, con excepción del otro dentro de unos 46 horas.
		Examen de caídas : se observó los efectos con fuerza de 1,2 uforas (Grado de Tensión T) por medio de estíngues de presión los cuales indican superficie horizontal y velocidad horizontal Pintura Caída : de plomo sobre la parte superior de la mesa Sistema Caída : de plomo sobre la parte superior de la mesa Tercera Caída : de plomo sobre una de las tablas laterales de la mesa Cuarta Caída : de plomo sobre uno de los lados más cercanos de la mesa Quinta Caída : sobre una esquina

HOJA	DE	INFORME N°:	INGENIERO DE ENSAYOS:
3	10	E91101	<i>A. M. Pérez</i>

FECHA	HORA	OBSERVACIONES
19/12/04	06:00	Sr. realizó la inspección de los cuchillajes Clas. Cl-2 y Cl-3 y tomó el peso neto en los informes realizados.
		Debido a las necesidades de Almacéndel, los cuchillos fueron enviados desde el 19 de diciembre de 2004 hasta el 12 de Enero de 2005 y las cifras de aplicación son de 28000
		yo como cada día fui una hora de 7:00 am en la certificación realizada los cuchillos en la casa no se distingue perdida de materiales ni se ha presentado nada indicativo de deficiencias alguna.
		Los cuchillajes están listos de acuerdo a los informes realizados por el Sr. Pérez.
		Cl-1: 450 Kg. Peso Neto: 270 Kg. Peso Bruto: 450 Kg.

HOJA	DE	INFORME N°:	INGENIERO DE ENSAYOS:
4	10	241101	<i>J. Pérez</i>

FECHA	HORA	OBSERVACIONES
19 - 12 - 04	Clase : 09:58 hs , 10:10 hs , 10:22 hs	
	Clase : 11:57 hs , 09:45 hs , 10:22 hs , 10:32 hs	
19 - 12 - 04	Sig. de procedimientos realizados:	
	Per lo cual se clavó con estacas el tuboaje hasta una altura de 1200 mm, dejándole espacio suficiente para que el horizontalmente en dirección noreste-suroeste.	
	ENSAYO CL-1	
	Prueba Carga - De plomo sujeta al fondo en los casilleros	
	El resultado es que se validó el tuboaje en su totalidad en todos los tipos en su posición.	

HOJA 5 DE 10 INFORME N°: 241101

INGENIERO DE ENSAYOS:

Alvaro

FECHA	HORA	OBSERVACIONES
12-01-07	5:00:00 AM - 06:00:00 AM	SEGUNDA CAIDA - El piano sigue en piezas separadas por la caida El mueble no pierde su unidad estructural, mantiene todos los clips en su posición, numeros uno y seis se salen un poco
	7:00:00 AM - 08:00:00 AM	TERCERA CAIDA - El piano sigue en piezas separadas por la caida El mueble no pierde su unidad estructural, mantiene todos los clips en su posición
	9:00:00 AM - 10:00:00 AM	CUARTA CAIDA - El piano sigue en piezas separadas por la caida El mueble no pierde su unidad estructural, mantiene todos los clips en su posición
	11:00:00 AM - 12:00:00 PM	QUINTA CAIDA : CONSEJO ESPAÑOL - Los costos - mantiene todos los clips en su posición El mueble no pierde su unidad estructural, mantiene todos los clips en su posición
	1:00:00 PM - 2:00:00 PM	EL mueble de madera se desplaza al fondo un poco las chapas de chaparón quedan pegadas el otro lado del soletón quedando la madera se salen los clips y quedan fijadas al suelo

HOJA	DE	INFORME N°:	INGENIERO DE ENSAYOS:
6	10	241101	J. J. Gómez

FECHA	HORA	OBSERVACIONES
12-01-04		de material
		Quinta Calzada - Sociedad de Caminos - Lado izquierdo - Paseo de la Constitución
		Se observaron agujas postizas para evitar que se pierda el suelo de la pista
		Significó facilidad para el tránsito
		Quinta Calzada - Sociedad de Caminos
		Se observaron tres tipos, posteriormente se vio que el terreno tiene una la calida y piedra que son consideradas de mala calidad
14-01-04	5:45:15 AM	Quinta Calzada - De Plano hacia el fondo de la carretera
		El pavimento es muy grueso y oxidado estructural se observa algo clínico
		y una gran parte es roto y se pierde producto incrementando el factor centrado en el fondo de la carretera

HOJA	DE	INFORME N°:	INGENIERO DE ENSAYOS:
7	10	241101	<i>J. Pérez</i>

FECHA	HORA	OBSERVACIONES
12-01-04	SEMANA CABA - DE PLANO SONORAE	(a) PARETE SUPERIOR DE LA CABA El tubo tiene una pieza de unidae estructural, que tiene una longitud de alrededor de 50 mm y que se encuentra en la parte superior de la pared interior.
	REFICAN CABA - DE PLANO SONORAE	DE ALGUNAS PIEZAS DE UNIDADE ESTRUCTURAL SE HA QUITADO UNA PARTE DEL TUBO PARA PODER VERIFICAR SI HABIA FRACTURA EN EL PRODUCTO EN ALGUNA UNIDAD.
	REFICAN CABA - DE PLANO SONORAE	DE ALGUNAS PIEZAS DE UNIDADE ESTRUCTURAL SE HA QUITADO UNA PARTE DEL TUBO PARA PODER VERIFICAR SI HABIA FRACTURA EN EL PRODUCTO EN ALGUNA UNIDAD.
	REFICAN CABA - DE PLANO SONORAE	DE ALGUNAS PIEZAS DE UNIDADE ESTRUCTURAL SE HA QUITADO UNA PARTE DEL TUBO PARA PODER VERIFICAR SI HABIA FRACTURA EN EL PRODUCTO EN ALGUNA UNIDAD.

HOJA 8 DE 10 INFORME N°: 241101

INGENIERO DE ENSAYOS: J. P. Pérez

FECHA	HORA	OBSERVACIONES
12-01-01		Se reduce el peso del embalaje hasta 200 kg en el caso de reponer la bomba Caja.
		Quinta caja - Se saca una bomba quemada - funcionamiento 65-70% El embalaje no pierde su unidad estructural, se retira los chips de la parte inferior, perdidos una bomba se certificó el producto. Los chips se vienen a caer en 5. posición apilamiento, el envase sigue
13-01-01	9 h 00'	Quinta Caja Primera Caja - No se pierde ninguna pieza en los chips El embalaje no pierde su unidad estructural, se retira los chips si una bomba rompe, las piezas quedan dentro del envase Segunda Caja - No pierde ninguna pieza en los chips El embalaje no pierde su unidad estructural, las bombas siguen

INFORME N°: 0410			INGENIERO DE ENSAYOS: <u>J. L. Jerez</u>
FECHA	HORA	OBSERVACIONES	
13 - 01 - 04	08:00	<p>TESTEADA CHIDA - DE PLAZA CON 1000 KG. SEAN SACAS DE LA CADA</p> <p>EL ensamble no pierde su calidad estructural mantenendose tal como fue fabricado.</p> <p>CASSETTE CUBA - DE PLAZA CON 1000 KG. SEAN SACAS DE LA CADA</p> <p>EL ensamble no pierde su calidad estructural manteniendo tal como</p> <p>clases de operación, y al momento que se realiza sufrido da producto</p> <p>ALIMENTO CHIDA - SUGAR AND SODA - INDUSTRIAL YERONE 250</p> <p>EL ensamble pierde su calidad estructural y sustituye por otra</p> <p>que perdio su forma y calidad por el efecto del calor o la presión del producto que se realizó la operación de la cama.</p> <p>SE REDUCE EL COSTO DE LA ESTILOTA 0.73 A \$00.450</p> <p>QUINTA CADAS - SOURCE UNA ESCUELA</p> <p>EL ensamble no pierde su calidad estructural, se muestra los efectos de la parte inferior del ensamble que se observa una diferencia</p>	

INGENIERO DE ENSAYOS:
INFORME N°: 27110 /
HOJA 10 DE 10

INFORME N°: 241101

HOJA 1 DE 10 INFORME N°: 24110 / INGENIERO DE ENSAYOS: 

FECHA	HORA	OBSERVACIONES
12-01-04	prediccion	Los clips se mueven en su posición normal el cubilete sigue flotando

APPENDIX II

**DISPOSICIONES SOBRE MERCANCIAS PELIGROSAS EN
EL TRANSPORTE AEREO (MOPT)**

Capítulo 4 – Ensayos de Idoneidad de los Embalajes.

7-4-1



Capítulo 4

ENSAYOS DE IDONEIDAD DE LOS EMBALAJES

Notas de introducción

Nota 1.—Los ensayos de idoneidad especificados en este capítulo tienen en cuenta el material utilizado y el diseño de los embalajes. También tienen en cuenta si las mercancías que haya que transportar son líquidos o sólidos.

Nota 2.—Los ensayos de idoneidad se hacen con la idea de garantizar que no haya pérdida del contenido en las condiciones normales de transporte. La rigurosidad de los ensayos de los embalajes depende del contenido que tenga que alojar, teniendo en cuenta el grado de peligrosidad (es decir, el grupo de embalaje), la densidad relativa y la presión de vapor (en cuanto a los líquidos).

4.1 ENSAYOS DE IDONEIDAD Y FRECUENCIA DE ÉSTOS

4.1.1. Cada prototipo de embalaje tiene que ensayarse de conformidad con lo previsto en este capítulo y con los procedimientos prescritos por la autoridad nacional que corresponda.

4.1.2. Antes de que pueda utilizarse un embalaje, su prototipo tiene que superar los ensayos de rigor. Se entiende por prototipo: el proyecto, tamaño, material y espesor, modo de construcción y empaque, que puede comprender diversos acabados de la superficie. También incluye los embalajes que difieran del prototípico sólo en su altura más baja.

4.1.3. Los ensayos tienen que repetirse en muestras de producción a intervalos fijados por la autoridad nacional que corresponda. En cuanto a los ensayos de los embalajes de papel o de cartón prensado, se considera que la preparación en las condiciones ambientales equivale a lo previsto en 4.2.3.

4.1.4. También tienen que repetirse los ensayos después de cada modificación que altere el proyecto, material o sistema de construcción del embalaje.

4.1.5. La autoridad nacional que corresponda puede permitir los ensayos seleccionados de embalajes que difieran únicamente en pequeños aspectos con relación al tipo ensayado, por ejemplo, con embalajes interiores de menor tamaño o embalajes interiores de menor masa neta; y los embalajes tales como los bidones, sacos y cajas que se construyen con pequeñas reducciones de sus dimensiones externas.

4.1.6. Cuando un embalaje exterior o un embalaje combinado ha superado los ensayos de idoneidad con diferentes tipos de embalajes interiores, también es posible poner en el embalaje exterior una variedad de esos embalajes interiores.

4.1.7. En cualquier momento, la autoridad nacional que corresponda puede exigir pruebas, mediante ensayos realizados de conformidad con lo previsto en este capítulo, de que los embalajes de producción satisfacen los mismos ensayos efectuados con el prototípico.

4.1.8. Si por razones de seguridad se requiere algún tratamiento interior o capa de revestimiento, éste debe retener sus propiedades protectoras aun después de hechos los ensayos.

4.1.9. Todo embalaje que tenga que contener líquidos tiene que pasar el ensayo de estanquidad prescrito en 4.4.2 a 4.4.4.:

- a) antes de que se utilice para el transporte;
- b) después de reacondicionarse, antes de que se use de nuevo para el transporte.

Este ensayo no es necesario en cuanto atañe a los embalajes interiores de embalajes combinados.

7-4-2

4.1.10 Pueden utilizarse métodos de ensayo distintos de los descritos en estas Instrucciones, siempre que sean equivalentes.

4.2 PREPARACIÓN DE LOS EMBALAJES PARA LOS ENSAYOS

4.2.1 Los ensayos tienen que realizarse con embalajes preparados para el transporte, incluyendo los embalajes interiores de los embalajes combinados. Los recipientes o embalajes interiores o únicos tienen que estar llenos, por lo menos, al 95 por 100 de su capacidad en cuanto a los sólidos y al 98 por 100 en cuanto a los líquidos. Las sustancias que tengan que transportarse en los embalajes pueden reemplazarse por otras sustancias, a menos que esto invalide el resultado de los ensayos. En cuanto a los sólidos, si se utiliza alguna otra sustancia tiene que tener las mismas características físicas (masa, tamaño de los granos, etc.) que la sustancia que habrá de transportar. Es posible utilizar aditivos, tales como sacos de perdigones, para conseguir la masa total prescrita, de modo que estén colocados de forma que no invaliden los resultados de los ensayos.

4.2.2 En los ensayos de caídas aplicables a los líquidos, cuando se utilice otra sustancia, su densidad relativa y viscosidad deberían ser iguales a las de la sustancia que haya que transportar. También se puede utilizar agua para hacer el ensayo de caída de líquidos en las condiciones previstas en 4.3.4.

4.2.3 Los embalajes de papel o de cartón prensado tienen que condicionarse por lo menos 24 horas en una atmósfera que tenga una temperatura y humedad relativa (h.r.) controladas. Hay tres posibilidades, entre las cuales hay que elegir una de

ellas. La atmósfera preferida es de $23^{\circ}\text{C} \pm 2^{\circ}\text{C}$ y $50\% \pm 2\%$ h.r. Las otras dos posibilidades son: $20^{\circ}\text{C} \pm 2^{\circ}\text{C}$ y $65\% \pm 2\%$ h.r. ó $27^{\circ}\text{C} \pm 2^{\circ}\text{C}$ y $65\% \pm 2\%$ h.r.

4.2.4 Hay que tomar las medidas necesarias para cerciorarse de que el plástico utilizado en la fabricación de bidones de plástico, jerricanes de plástico y embalajes compuestos (materiales de plástico) se ajusta a lo previsto en la Parte 3;1.1.3, Parte 7;3.1.6.1 y Parte 7;3.1.6.4. Por ejemplo, esto puede hacerse sometiendo muestras de recipientes o embalajes a un ensayo preliminar por un largo período de tiempo, tal como seis meses, durante los cuales las muestras tienen que permanecer llenas de las sustancias que tengan que contener, y después de lo cual las muestras tienen que someterse a los ensayos previstos en 4.3, 4.4, 4.5 y 4.6. En cuanto a las sustancias que puedan causar quebraduras o debilitar los bidones o jerricanes de plástico, la muestra, con la sustancia o alguna otra sustancia que se sepa que produce quebraduras en el material plástico en cuestión, debe someterse a una carga adicional equivalente a la masa total de bultos idénticos que tengan que apilarse sobre ella durante el transporte. La altura mínima de apilamiento, incluyendo la muestra de ensayo, debe ser de 3 m.

4.3 ENSAYO DE CAÍDA

4.3.1 Número de muestras de ensayo (por prototipo y fabricante) y dirección de caída

Cuando no se trata de caídas sobre superficies planas, el centro de gravedad debe estar situado verticalmente sobre el punto de impacto.

Embalajes	Número de muestras	Dirección de la caída
Bidones de acero	Seis (tres por caída)	Primera caída (tres muestras): el embalaje tiene que golpear diagonalmente el objetivo con el reborde o, si no tiene reborde, con una costura circumferencial o con el borde.
Bidones de aluminio		
Jerricanes de acero		
Bidones de madera contrachapada		
Bidones de cartón		
Bidones y jerricanes de plástico		
Embalajes compuestos en forma de bidón		Segunda caída (con las otras tres muestras): el embalaje tiene que golpear el objetivo por el punto más débil no ensayado con la primera caída; por ejemplo, una tapa o, en el caso de algunos bidones cilíndricos, la costura longitudinal soldada del cuerpo del bidón.
Cajas de madera natural	Cinco (una por caída)	Primera caída: de plano sobre el fondo de la caja
→ Cajas de madera contrachapada		Segunda caída: de plano sobre la parte superior de la caja
Cajas de madera reconstituida		Tercera caída: de plano sobre uno de los lados más largos de la caja
Cajas de cartón prensado		Cuarta caída: de plano sobre uno de los lados más cortos de la caja
Cajas de plástico		Quinta caída: sobre una esquina.



<i>Embalajes</i>	<i>Núm. de muestras</i>	<i>Direccion de la caída</i>
Cajas de acero o de aluminio Embalajes compuestos en forma de caja		
Sacos de una sola capa sin costura lateral, o multicapas	Tres (dos caídas por saco)	Primera caída: de plano sobre la cara frontal del saco Segunda caída: sobre un fondo del saco.
Sacos de una sola capa con costura lateral	Tres (tres caídas por saco)	Primera caída: de plano sobre la cara frontal del saco Segunda caída: de plano sobre un lado del saco Tercera caída: sobre un fondo del saco.

4.3.2 Preparación especial de las muestras de ensayo para hacer el ensayo de caída

Es necesario hacer ensayos con los bidones, jerricanes y cajas de plástico (véase 3.1.6 y 3.1.11), con los embalajes compuestos (plástico) (véase 3.1.17) y con los embalajes combinados, con embalajes interiores de plástico — con excepción de los sacos y de las cajas de poliestireno expandido cuando la temperatura de la muestra de ensayo y de su contenido se ha reducido a -18°C o menos; cuando las muestras de ensayo se han preparado de esta manera, se puede prescindir del acondicionamiento previsto en 4.2.3. Los líquidos de ensayo tienen que preservarse en estado líquido, si es necesario añadiendo un anticongelante.

4.3.3 Blanco

El blanco consistirá en una superficie rígida, que no sea elástica, plana y horizontal.

4.3.4 Altura de caída

En cuanto a los sólidos y líquidos, si el ensayo se realiza con el sólido o líquido que haya que transportar o con alguna otra sustancia que tenga esencialmente las mismas características físicas:

<i>Grupo de embalaje I</i>	<i>Grupo de embalaje II</i>	<i>Grupo de embalaje III</i>
1,8 m	1,2 m	0,8 m

En cuanto a los líquidos, si el ensayo se hace con agua:

- a) cuando las sustancias que haya que transportar tengan una densidad relativa que no exceda de 1,2:

<i>Grupo de embalaje I</i>	<i>Grupo de embalaje II</i>	<i>Grupo de embalaje III</i>
1,8 m	1,2 m	0,8 m

- b) cuando las sustancias que haya que transportar tengan una densidad relativa que excede de 1,2, la altura de caída debe calcularse a base de la densidad relativa de la sustancia que haya que transportar, redondeada hasta el decimal más próximo, así:

<i>Grupo de embalaje I</i>	<i>Grupo de embalaje II</i>	<i>Grupo de embalaje III</i>
densidad relativa $\times 1,5$ (m)	densidad relativa $\times 1,0$ (m)	densidad relativa $\times 0,67$ (m)

4.3.5 Criterios de superación del ensayo

4.3.5.1 Todo embalaje que contenga algún líquido no puede tener filtraciones una vez se haya logrado el equilibrio entre las presiones interna y externa, con excepción de los embalajes

interiores de embalajes combinados, en cuyo caso no es necesario que las presiones sean iguales.

4.3.5.2 Cuando un embalaje que contiene sólidos se somete al ensayo de caída y la parte superior toca el blanco, la

7-4-4

muestra de ensayo supera el ensayo si el contenido queda retenido en un embalaje o receptáculo interior (por ejemplo, un saco de plástico), aún cuando la tapa ya no evite el tamizado.

4.3.5.3 El embalaje o el embalaje exterior de un embalaje compuesto o combinado no tiene que tener absolutamente avería alguna que pueda afectar la seguridad al transportarlo. No puede haber fugas de la sustancia que llena el receptáculo interior a los embalajes interiores.

4.3.5.4 La capa externa de un saco o del embalaje exterior no deben tener averías que puedan afectar la seguridad al transportarlos.

4.3.5.5 Una ligera pérdida, a través del cierre o cierres, al chocar, no hace defectuoso el embalaje, con tal que no ocurran más pérdidas.

4.3.5.6 En cuanto a los embalajes para mercancías de la Clase I, no debe haber ninguna rotura que permita el derrame de sustancias o artículos explosivos sueltos fuera del embalaje exterior.

4.4. ENSAYO DE ESTANQUIDAD

Este ensayo tiene que realizarse con todos los tipos de embalajes que tengan que contener líquidos; sin embargo, este ensayo no es necesario respecto a los embalajes interiores combinados.

4.4.1 Número de muestras de ensayo: tres muestras por prototipo y fabricante.

4.4.2 Método de ensayo y presión que hay que aplicar: por lo que atañe a los ensayos del prototipo, los embalajes, incluyendo los cierres, tienen que hacerse sumergidos en agua mientras se aplica internamente presión de aire; este método de precaución no debe afectar los resultados del ensayo. También es posible recurrir a otros métodos que no sean por lo menos tan eficaces como éste. La presión de aire (de manómetro) que hay que aplicar tiene que ser:

- *Grupo de embalaje I*
Como mínimo 30 kPa
- *Grupo de embalaje II*
Como mínimo 20 kPa
- *Grupo de embalaje III*
Como mínimo 20 kPa

4.4.3 En cuanto al ensayo de estanquidad previsto en 4.1.9, no es necesario que los embalajes lleven sus propios cierres. Cada embalaje tiene que ensayarse según lo previsto en 4.4.2.

4.4.4 Criterio de superación del ensayo: no puede haber pérdidas.

4.5 ENSAYO DE PRESIÓN INTERNA (HIDRÁULICA)

4.5.1 Embalajes sometidos a ensayo: el ensayo de presión interna (hidráulica) tiene que realizarse en relación con todos los embalajes de metal, de plástico y compuestos que tengan que contener líquidos; no obstante, este ensayo no es esencial para los embalajes interiores que forman parte de embalajes combinados. Con respecto a los requisitos sobre presión interna de los embalajes interiores, véase la Parte 3;1.1.6.1.

4.5.2 Número de muestras de ensayo: tres muestras por prototipo y fabricante.

4.5.3 Método y presión de ensayo que hay que aplicar: los embalajes metálicos incluyendo sus cierres respectivos, deben someterse por 5 minutos al ensayo de presión. Los embalajes de plástico y los compuestos (plástico), incluyendo sus cierres, tienen que someterse por 30 minutos al ensayo de presión. La forma en que se apoyan los embalajes no debe invalidar el ensayo. El ensayo de presión debe hacerse en forma constante durante todo el período de ensayo. La presión hidráulica (manómetro) aplicada debe ser:

a) no inferior a la presión total de manómetro medida del embalaje (es decir, la presión de vapor de la sustancia contenida y la presión parcial del aire u otro gas inerte, menos 100 kPa) a 55 °C multiplicados por un factor de seguridad de 1,5. Esta presión total de manómetro debe determinarse a base del grado máximo de llenado, de conformidad con la Parte 3;1.1.5 y una temperatura de llenado de 15 °C. La presión de ensayo no debe ser inferior de 95 kPa (no menos de 75 kPa para los líquidos del Grupo de embalaje III, Clase 3, o de la División 6.1); o bien

b) no menos de 1,75 veces la presión de vapor a 50 °C de la sustancia que haya que transportar, menos 100 kPa, pero con una presión mínima de ensayo de 100 kPa; o bien

c) no menos de 1,5 veces la presión de vapor a 55 °C de la sustancia que haya de transportar, menos 100 kPa, pero con una presión mínima de ensayo de 100 kPa.

Todo eso se expresa así:

$$a) P_T = (P_{M_{55}} \times 1,5) \text{ kPa con mínimos de 95 ó 75 kPa;}$$

$$b) P_T = (V_{P_{50}} \times 1,75) \text{ — con un mínimo de 100 kPa;}$$

$$c) P_T = (V_{P_{55}} \times 1,5) \text{ — con un mínimo de 100 kPa;}$$


fórmulas en las que:

$$P_T = \text{Presión de ensayo en kPa (manómetro)}$$

$$P_{M_{55}} = \text{Presión medida en el embalaje llenado a temperatura de } 55^{\circ}\text{C.}$$

$$V_{P_{50}} = \text{Presión del vapor a } 50^{\circ}\text{C}$$

$$V_{P_{55}} = \text{Presión del vapor a } 55^{\circ}\text{C.}$$



7-4-5

4.5.4 Además de esto, los embalajes que tengan que contener líquidos pertenecientes al Grupo de embalaje I deben ensayarse a una presión mínima de ensayo de 250 kPa (manómetro) por un período de 5 ó 30 minutos, según sea el material de que está compuesto el embalaje.

4.5.5 Criterio de superación del ensayo: el embalaje no debe tener pérdidas.

4.6 ENSAYO DE APILAMIENTO

4.6.1 Todos los embalajes, exceptuados los sacos, tienen que someterse al ensayo de apilamiento.

4.6.2 Número de muestras de ensayo: tres muestras de ensayo por prototipo y fabricante.

4.6.3 Métodos de ensayo: La muestra de ensayo tiene que someterse a una fuerza aplicada a la superficie superior de la muestra de ensayo, equivalente al peso total de embalajes idénticos que podrían apilarse en ella durante la operación de transporte: cuando el contenido de las muestras de ensayo sean líquidos, que no encierren peligro, de una densidad relativa dife-

rente de la del líquido que haya que transportar, la fuerza tiene que calcularse en relación con el último. La altura mínima del apilamiento, incluyendo la muestra de ensayo, tiene que ser de 3 m. El ensayo debe durar 24 horas excepto cuando se trata de bidones, jerricanes y embalajes compuestos (6HH1 y 6HH2) de plástico que tengan que llevar líquidos, en cuyo caso tienen que someterse a la prueba de apilamiento por un período de 28 días y a una temperatura mínima de 40°C.

4.6.4 Criterios de superación del ensayo: las muestras de ensayo no deben tener pérdidas. Cuando se trata de embalajes compuestos o combinados, no puede haber pérdidas de la sustancia que los ocupa, a partir del recipiente interior o del embalaje interior. Las muestras de ensayo no pueden dar indicios de deterioro, que pueda afectar adversamente la seguridad de transporte, o de distorsión alguna que pueda disminuir su resistencia o causar la inestabilidad del apilamiento de bultos. En aquellos casos (como los ensayos controlados de carga de bidones y jerricanes), cuando la estabilidad del apilamiento se evalúa una vez completado el ensayo, esto puede considerarse suficiente cuando dos embalajes del mismo tipo llenos y colocados en cada muestra de ensayo mantienen su posición por una hora. Antes de hacer la evaluación, los embalajes de plástico tienen que refrigerarse a la temperatura ambiente.

